



All products that are received will incur a minimum \$95 diagnostic fee that will be applied to any repair.



- MVP-50T - Bench Test Fee* \$295
- MVP-50T - Repairs *without* New Display \$695
- MVP-50T - Repairs *including* New Display \$1,695



- MVP-50P - Bench Test Fee* \$295
- MVP-50P - Repairs *without* New Display \$495
- MVP-50P - Repairs *including* New Display \$1,495



- CGR-30P/C - Bench Test Fee* \$295
- CGR-30P/C - Repairs *without* New Display \$495
- CGR-30P/C - Repairs *including* New Display \$895



- EDC-33P - All Repairs \$295
- EDC-33T - All Repairs \$495



- UBG Instruments - Recalibrate, Bench Test, Repairs *without* New Display \$125
- UBG Instruments - Recalibrate, Bench Test, Repairs *including* New Display \$265

- Most Other Instruments - Recalibrate, Bench Test, Repairs *without* New Display \$125
- Most Other Instruments - Recalibrate, Bench Test, Repairs *including* New Display \$195

- Most Other Turboprop Instruments - Recalibrate, Bench Test, Repairs *without* New Display \$295
- Most Other Turboprop Instruments - Recalibrate, Bench Test, Repairs *including* New Display \$395

- Probes and Transducers - Bench Test* \$65
- Probes and Transducers - Replacement (Must have been purchased within the last 5 years.) 50% Retail

Repair 8130-3 Airworthiness Approval Tag \$95

NIST Traceability available, contact EI for details and pricing.

* Bench Test Fee will be applied toward any necessary repairs. Please note that all bench tests will include small repairs and standard upgrades if available.

