



U.S. Department
of Transportation
**Federal Aviation
Administration**

**Transport Airplane Directorate
Aircraft Certification Service**

1601 Lind Avenue S.W.
Renton, Washington 98055-4056

NOV 18 1997

In Reply
Refer To: 97-190S-721

Mr. Ron Roberts
President
Electronics International, Inc.
12620 SW 231st Place
Hillsboro, OR 97123

Dear Mr. Roberts:

This is in regard to your letter and application for supplemental type certificate (STC), both dated November 11, 1997, for replacement clocks to be installed in small airplanes. We consider this change to be minor in accordance with Federal Aviation Regulation (FAR) 21.93(a). Accordingly, an STC is not required to install Electronics International clocks in non-transport category airplanes. Per FAR 21.95 copies of this letter may be given to installing mechanics as evidence that this installation is considered minor.

Since an STC is not required, we are returning your data submittal and application. If you have any questions regarding this matter please contact Mr. Jeff Morfitt of this office at (425) 227-2595.

Sincerely,

A handwritten signature in black ink, appearing to read 'A. J. Pasion', with a large, loopy flourish above the name.

A. J. Pasion
Manager, Special Certification Branch
Seattle Aircraft Certification Office

Enclosures